



Nat RE Proj

Photo No 117

file 0.431

7/3/29

by Geo Kable

Jones showing burned end of cable  
on Jones farm - damaged done by  
lightning.

Fault located within one foot with  
detector (coil & headphones with interrupter  
and high voltage



